

C16-M-406

6451

BOARD DIPLOMA EXAMINATION, (C-16) SEPTEMBER/OCTOBER - 2020 DME—FOURTH SEMESTER EXAMINATION

PRODUCTION DRAWING

Time: 3 hours] [Total Marks: 60

PART—A

 $5 \times 4 = 20$

Instructions: (1) Answer **all** questions.

- (2) Each question carries five marks.
- 1. The dimensions of a shaft and a hole are given below:

0 002

Shaft 50 0001 Hole 50 0 0010

Find out the maximum allowance and hole tolerance. $2\frac{1}{2}+2\frac{1}{2}=5$


- 2. Draw the symbolic representation for the following geometrical characteristics to be toleranced: 5
 - (a) Straightness
 - (b) Squareness
 - (c) Symmetry
 - (d) Angularity
 - (e) Cylindricity

/6451 1 [Contd...

3.		icate the surface roughness limiting values for the followin nufacturing processes :	g 5
	(a)	Die casting	
	(b)	Forging	
	(c)	Turning and milling	
	(d)	Boring	
	(e)	Reaming	
4.		te the meaning for the code designation of the followin aponents : $2\frac{1}{2}+2$	_
	(a)	Taper key 15 10 70	
	(b)	Hex bolt M10 40NL	
		DADT D	40
Inst	ruct	PART—B	40
Inst	ruct	tions: (1) Answer any one question.	40
Inst	ruct	tions: (1) Answer any one question. (2) Each question carries forty marks.	40
Inst	ruct	tions: (1) Answer any one question.	40
		(2) Each question carries forty marks. (3) All dimensions are in mm.	40
	Stu	(2) Each question carries forty marks. (3) All dimensions are in mm. (4) Choose suitable scale.	40
	Stu	(2) Each question carries forty marks. (3) All dimensions are in mm. (4) Choose suitable scale.	40
	Stu (a) (b)	(2) Each question carries forty marks. (3) All dimensions are in mm. (4) Choose suitable scale. ddy the given assembly drawing of the knuckle joint and— draw the component drawings;	40

- (d) show the surface roughness symbols;
- (e) list out the materials for the components;
- (f) prepare the process sheet for pin.


20+5+3+3+4+5=40



Bill of material

Part No.	Name	Qty.
1.	Fork end	1
2.	Eye end	1
3.	Pin	1
4.	Collar	1
5.	Taper pin	1

- **6.** Study the given assembly drawing of the bushed pin-type flanged coupling and—
 - (a) draw the component drawings;
 - (b) apply suitable tolerances and fits;
 - (c) apply suitable geometrical tolerances to components;
 - (d) show the surface roughness symbols;
 - (e) list out the materials for the components;
 - (f) prepare the process sheet for flange 2. 20+5+3+3+4+5=40



Bill of material

Part No.	Name	Qty.
1.	Flange	1
2.	Flange	1
3.	Shaft	2
4.	Key	2
5.	Rubber bushes	
6.	Bolt	4

* * *

/6451 4 AA20—PDF