

C09-M-105/C09-RAC-105

3043

BOARD DIPLOMA EXAMINATION, (C-09) OCT/NOV-2016 DME-FIRST YEAR EXAMINATION

WORKSHOP TECHNOLOGY

Time: 3 hours [Total Marks: 80

PART—A

 $3 \times 10 = 30$

Instructions: (1) Answer **all** questions.

- (2) Each question carries three marks.
- (3) Answers should be brief and straight to the point and shall not exceed *five* simple sentences.
- 1. List out any three types of surface treatment processes.
- 2. Draw a neat sketch of coping saw and state its purpose.
- 3. What are the uses of depth gauge?
- 4. Write short notes on the following:
 - (a) Ball-peen hammer
 - (b) Cross-peen hammer
- **5.** What is a soldering iron? List two types of soldering iron.
- **6.** List any three advantages of synthetic sands over natural sands.
- **7.** State the applications of CO_2 process.

/**3043** [Contd...

- **8.** Draw a segmental pattern.
- 9. What are the specifications of drilling machine?
- **10.** State the limitations of hot extrusion process.

PART—B

 $10 \times 5 = 50$

Instructions: (1) Answer any **five** questions.

- (2) Each question carries **ten** marks.
- (3) Answers should be comprehensive and the criterion for valuation is the content but not the length of the answer.
- **11.** Explain the working of circular saw with a neat sketch.
- **12.** What is a chisel? Explain any four types of chisel with neat sketches.
- **13.** Name the different types of power hammers. Explain the working of steam hammer.
- **14.** (a) What is meant by flanging and burring as applied to sheet metal work?
 - (b) Briefly explain spot welding with sketch.
- **15.** (a) State the advantages and limitations of casting over other manufacturing process.
 - (b) Sketch any three hand tools commonly used by moulder.
- **16.** (a) Draw a neat sketch of twist drill and label the various parts.
 - (b) List various materials used for drills.
- **17.** Explain the working principle of friction disc sawing. Why is it not suitable for cast iron?
- **18.** What are the advantages and disadvantages of hot working over cold working?

* * *

/**3043** 2 AA6(A)—PDF