

C16-M-106/RAC-106

6057

BOARD DIPLOMA EXAMINATION, (C-16) MARCH/APRIL—2017

DME—FIRST YEAR EXAMINATION

WORKSHOP TECHNOLOGY

Time : 3 hours]

[Total Marks : 80

PART—A

3×10=30

Instructions : (1) Answer **all** questions.

- (2) Each question carries three marks.
- (3) Answers should be brief and straight to the point and shall not exceed *five* simple sentences.
- 1. List out different holding tools used in carpentry.
- 2. What is the difference between reaming and drilling?
- **3.** Draw a neat sketch of hand hammer and name the parts.
- 4. Write the differences between punching and drifting.
- 5. What are the common six defects of forging?
- 6. List out the three types of hems.
- 7. State the properties of good moulding sand.
- **8.** What is meant by sand binder? Name the types of sand binders.
- 9. Write about hot extrusion process.
- **10.** Describe the wire drawing process with a neat sketch.

/6057 1 [Contd... WWW.MANARESULTS.CO.IN

Instructions : (1) Answer any **five** questions.

*

- (2) Each question carries **ten** marks.
- (3) Answers should be comprehensive and the criterion for valuation is the content but not the length of the answer.
- **11.** (*a*) Draw a neat sketch of metal jack plane and name its parts. 5
 - (b) Write the specific use of (i) spoke shave and (ii) router plane. 5
- **12.** List out the different types of files. Write the use of any three types of files with sketches.
- **13.** Describe the working of spring hammer with a neat sketch.
- **14.** Draw neat sketches of any four types of stakes used in sheet metal shop and explain their use.
- 15. (a) Draw a neat sketch of twist drill and name the parts.
 (b) List the various materials used for drills.
 5
- **16.** Explain dry sand moulding. Write the advantages and disadvantages and its applications.
- 17. Describe the following cold working processes :
 - (a) Spinning
 - (b) Shot peening
 - (c) Cold heading
 - (d) Cold extrusion
- **18.** (a) List the specifications of a power hack saw.
 - (b) What is setting saw teeth? Explain the types of setting with sketches.

* * *

/6057